

1/4





FIG. 1



2/4





FIG. 2



3/4




FIG. 3





FIG. 4



4/4

$i=0$	q		$i=8$		q		$i=16$		q		$i=24$		q		
	...7	8	16	...15	8	16	...23	8	16	...31	8	16	...31	8	16
[13] [00]	C_0 00	C_0 0	[33] [02]	C_0 01	C_2 1	[31] [00]	C_5 00	C_8 0	[11] [02]	C_5 01	C_{10} 1				
[12] [10]	C_1 00	C_1 0	[32] [12]	C_1 01	C_3 1	[30] [10]	C_4 00	C_9 0	[10] [12]	C_4 01	C_{11} 1				
[11] [20]	C_0 10	C_2 0	[31] [22]	C_0 11	C_0 1	[33] [20]	C_5 10	C_{10} 0	[13] [22]	C_5 11	C_8 1				
[10] [30]	C_1 10	C_3 0	[30] [32]	C_1 11	C_1 1	[32] [30]	C_4 10	C_{11} 0	[12] [32]	C_4 11	C_9 1				
[03] [01]	C_3 00	C_5 0	[23] [03]	C_3 01	C_7 1	[21] [01]	C_6 00	C_{13} 0	[01] [03]	C_6 01	C_{15} 1				
[02] [11]	C_2 00	C_4 0	[22] [13]	C_2 01	C_6 1	[20] [11]	C_7 00	C_{12} 0	[00] [13]	C_7 01	C_{14} 1				
[01] [21]	C_3 10	C_7 0	[21] [23]	C_3 11	C_5 1	[23] [21]	C_6 10	C_{15} 0	[03] [23]	C_6 11	C_{13} 1				
[00] [31]	C_2 10	C_6 0	[20] [33]	C_2 11	C_4 1	[22] [31]	C_7 10	C_{14} 0	[02] [33]	C_7 11	C_{12} 1				

FIG. 5